Work	Order	ID	63959
------	-------	----	-------

Monday, November 22, 2010 9:52:12 AM



Page 1

Item ID: Revision In: D3827-041

Rib Assembly (Inboard) Item Name:

**Start Date:** 

11/22/2010 Start Qty: 6.00

**Required Date:** 11/29/2010 Req'd Qty: 6.00



Accept

Setup Start

Stop



Reference:

**Approvals:** 

QC:

Date: 10-11-22 Tooling:

Date:

0.00

0.00

SPC (Y/N):

Date:

**Cust Item ID:** 

**Customer:** 

Date:

Run Start

Stop



Sequence ID/ Work Center ID

Operation Description

**Revision Nbr** 

Set Up/ **Run Hours**  **Tool ID** 

Tool # Plan Code Accept **Qty** 

Reject Qty

Reject Insp. Number Stamp

D3827

Rev A

100

**Draw Nbr** 

Large Fab

Large Fab

Large Fab

Memo

1- cut D3827-1 rib as per dwg D3827

2- drill holes using DT9435 jig and open to finish size as per dwg D3827

3- c'sink as per dwg

4- remove identification markings

5- deburr

6- weld bushing in rib as per dwg D3827 A/R S.S. Rod Batch:

7- grind weld flush

8- deburr if necessary

W/O:			WC	ORK ORDER CHANGE	S	<del></del>			i,		
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
								1 Tod Wigi			
<del></del>											
		•									
Part No	•	PAR #:	Fault Cate	NCR: Yes	NCR: Yes No DQA: Date:						
	Re	esolution:	Dispositio	n:	QA: N/C CI	QA: N/C Closed: Date: _					
NCR:			WORK ORD	ER NON-CONFORMA	NCE (NCR	)					
DATE	STEP	Description of NC		n B	Verific		Approval Chief Eng	Approval			
DAIL	JILI	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date			QC Inspector			
									7		
				•					ļ		
									:		

Work Order ID 63959  Monday, November 22, 2010 9:52:12 AM												Page 2	
Revisio ID: Revisio ID: Item Name: Rib Assembly (Inboard) Start Date: 11/22/2010 Start Qty: 6.00 Required Date: 11/29/2010 Req'd Qty: 6.00 Reference:					Cust Item ID: Customer:		Setup					•	
Approvals:		n:				nte:		F	Run	Start Stop		10 10 110 110 1 10 110 110 110 1	
Sequence ID/ Work Center II  130 QC Quality Control		Operation Description QC10- Inspect visual per Memo	r QS1004- ground welds	Set Up/ Run Hours 0.00	Tool ID	Tool#	Plan Code	Accept Qty	Reju Qty		Reject Number	Insp. Stamp	
140 		QC5- Inspect part comp	leteness to step on W/O	00.00 كريا	ızloz			(+6)	)	·			
150 Packaging		Identify as per dwg & St	tock Location: WA	0.00	3AD 10-17-08			(B)	<u></u>				

Packaging

<b>D</b> ail 710	. oopaoo	2.0								•
W/O:			WO	RK ORDER CHANG	GES					1
DATE	STEP	PRO	OCEDURE CHAI	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									`	
Part No	):	PAR #:	Fault Cate	gory:	_ NCR	: Yes N	10 <b>DQ</b> .	A:	Date:	
	Re	solution:	Disposition	n:	QA:	N/C Clo	sed:		Date: _	
NCR:		,	WORK ORDE	R NON-CONFORM	ANCE	(NCR)	)			
		Description of NC			tion B		Verific	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date		ion C	Chief Eng	QC Inspector
						<del> </del>				
						· · · · · · · · · · · · · · · · · · ·				

#### Work Order ID 63959

Page 3

Monday, November 22, 2010 9:52:12 AM

Item ID:

D3827-041

Revision ID:

Item Name:

Rib Assembly (Inboard)

Start Date:

11/22/2010

Start Oty: 6.00

**Required Date:** 11/29/2010

Req'd Qty: 6.00

**Operation** 

Description



Accept

Date:

Date:

Setup Start

Run

Stop

Reference:

Approvals:

Process Plan:

QC:

OC21- Final Inspection - Work Order Release

Date:\_\_\_\_\_

Date:

SPC (Y/N):

Tooling:

Set Up/

**Run Hours** 

Tool ID

**Cust Item ID:** 

Customer:

Tool # Plan

Qty Code

Accept

Reject Reject Number Qty

Start

Stop

Insp. Stamp

Sequence ID/ Work Center ID

160

Quality Control

Memo

0.00

0.00

W/O:		WORK ORDER CHANGES										
DATE	STEP	PRO	OCEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
							· · · · · · · · · · · · · · · · · · ·					
Part No	) <b>:</b>	PAR #:	PAR #: Fault Category:				_ NCR: Yes No DQA: D					
	Re	esolution:	Disposition	on:	QA:	N/C Clo	sed:		Date: _	·····		
NCR:			WORK ORD	DER NON-CONFORM	ANCE	(NCR)	)					
DATE	STEP	Description of NC	Corrective Action Secti			Ciam 0		cation	Approval	Approval		
DAIL	J.L.	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section C		Chief Eng	QC Inspector		
				-				··		1		

## Picklist Print

Monday, November 22, 2010 9:52:16 AM

Work Order ID: 63959

Parent Item:

D3827-041

Parer: Item Name: Rib Assembly (Inboc.d)



Start Date: 11/22/2 10

Required Date: 11/29/2016

Page 1

Start Qty: 6.00

Required Qty: 6.00

Comments:
-----------

IPP Rev: A 08-12-01 new issue DD verified by FC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3759-1		Manufactured	No			100	Each	40.0000	3	18//	10-18	1.07	
				Location ST084		Loc	<u>Qty</u> 21	Loc Code	T	6387	′S->	-(16	
				WA	56942		21				363	8-76-	<del>&gt;</del> (2)
					54072 61379		9		=		400		
M304TS0.750W.065		Purchased	No			100	f	386.6173		50.52632 SAD	wh	-9 U	
304 SQ Tube .75x.75x.065	W			<u>Location</u>	ı	<u>Loc</u>	<u>Qty</u>	Loc Code					1
				MAT	112398	286.8	38115 0		_				
					115494 115593		.4725 10865			50.5264	(		
,				WA	115274		36185 12185		_				


95.024

115901


W/O:			W	ORK ORDER CHANG	GES				¢					
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
									*					
								,						
Part No	:	PAR #:	Fault Cate	egory:	NCR: Yes No DQA: Date:									
	R	esolution:	Disposition	on:	QA: N/C	Closed: _		Date: _						
NCR:			WORK ORDER NON-CONFORMANCE (NCR)											
DATE	STEP	Description of NC	Initial		tion B		ication	Approval Chief Eng	Approval					
		Section A	Chief Eng	Action Description Chief Eng	Dat	e Sec	tion C		QC Inspector					
							-							
			;											

QTY -041 ITEM DESCRIPTION 1 D3827-041 RIB ASSY (INBOARD) 2 3 D375º 1 BUSHING D3827-1 3 1 RIB SHOP COlin RETURN TO ENGINEERING UNCONTROLLED COPY SUBJECT TO AMENDMENT WITHOUT NOTICE D3827-041 RIB ASSY (INBOARD) NEW ISSUE 08.09.23 REV. DESCRIPTION DATE DESIGN DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA NOTES:
1) MATERIAL: N/A
2) FINISH: NONE
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
6) IDENTIFICATION: N/A
7) WEIGHT: 4.59 lbs DRAWN CHECKED DRAWING NO. REV. A D3827 MFG. APPR. SHEET 1 OF 3 TITLE APPROVED SCALE RIB ASSY (INBOARD) DE APPR. NTS DATE 08.09.23 8

W/O:				,		ς.					
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
								. , oog.			
						•					
Part No	•	PAR #:	Fault Categ	NCR: Yes	NCR: Yes No DQA: Date:						
		esolution:									
NCR:			WORK ORDE	R NON-CONFORM	IANCE (NCR	)					
DATE	STEP	Description of NC			ction B	Verific		Approval	Approval		
DAIL	O.E.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section	on C	Chief Eng	QC Inspector		
4											
			1 1								



W/O:			W	ORK ORDER CHANGE	S			<b>(</b> .			
DATE	STEP	PRC	CEDURE CH	ANGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
							- Frod Migr				
						j					
Part No	•	PAR #:	NCR: Yes	NCR: Yes No DQA: Date:							
	R	esolution:	QA: N/C Clo	sed:	Date: _						
NCR:		\	WORK ORI	DER NON-CONFORMA	NCE (NCR	)					
DATE	STEP	Description of NC	Description of NC Correcti			Verification		Approval			
	JILI	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector			
					-						
		·									
		,									
						77,271					
•											



W/O:		WORK ORDER CHANGES									
DATE	STEP	PRO	CEDURE CHAI	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	'Approval QC Inspector	
			•	A <sub>s</sub>			`			•	
									÷		
Part No:	No: PAR ## Fault Category: NCR: Yes No DQA: Date:							_ Date: _			
	R	esolution:	Disposition: QA: N/C Closed: Da						Date:		
NCR: WORK ORDER NON-CONFORMANCE (NCR)					R)						
DATE	STEP	Description of NC		n Section B	1	Verific	ation	Approval	Approval		
DAIL	SILF	Section A	Initial Chief Eng	Action Des Chief E		Sign 8 Date	Section C		Chief Eng	QC Inspector	
į										*	
		*5									